
## Mounting guidelines PVC strip curtains



## 1. Compare parts delivered to packing list.

## 2. Installation:

Screw together supporting tubes (2) by means of joining piece (6) tightly (only necessary with regard to a strip curtain width of more than 6 m).

Blank off one tube end with plug (1) and slide pre-assembled holding sleeve (5), plastic tubes (3) and fastening clamps (4) on the supporting tube according to drawing. When doing so join the plastic tubes (respectively plastic tube + fastening clamp) in such a way that the below-mentioned distance "L" is kept. All fastening clamps included have to be distributed at regular intervals on the supporting tube. Fix pre-assembled strip curtain (corresponding to the according attachment). Then screw together the single strips and the holding sleeves (5) (attention is to be paid to the overlap width "E"). The terminal strip has to be screwed according to the opening width and to be provided with additional screw holes if necessary.

Size "L" = \_\_\_\_\_ Overlap "E" = \_\_\_\_\_

## Attachment B on beam IPE 100 according to DIN 1025 provided by the customer C in front of the lintel intel intel in front of the lintel in front of the lintel